



TSB NO.248  
DATE: 04 / 11 / 2002



---

## TECHNICAL SERVICE BULLETIN

**TO:** All RELM / Uniden PRC Communication Dealers,  
Distributors and Warranty Service Stations

**REFERENCE:** SMH1525DT & SMU4525KT

**SUBJECT:** Dwell Time Setting Disables the Monitor Function

---

**GENERAL:** It has been discovered that when selecting 150ms Dwell Time in the Scan Feature disables the Monitor Button. This is a minor bug with the AMX793 programming software.

**CORRECTION:** There is no updated version of the AMX793. We suggest that you use only 100ms or 200ms Dwell Time settings.

**WARRANT INFORMATION:** No warranty procedures are necessary with this TSB.

---

### RELM COMMUNICATIONS

7100 Technology Drive, West Melbourne, Florida 32904  
800-648-0947 – Email [service@RELM.com](mailto:service@RELM.com)