



TSB NO.249
DATE: 11 / 14 / 2002



TECHNICAL SERVICE BULLETIN

TO: All RELM / Uniden PRC Communication Dealers,
Distributors and Warranty Service Stations

REFERENCE: SMH250DT, SMU250KT & SMU250KTST

SUBJECT: Parts Correction in Service Manual

GENERAL: We have been informed of an error in the service manuals for the above models. The RF Schematic describes the WA902 as a W-072141 and WA901 as a W-072142. **Please make note that WA902 is actually the W-072142 and WA901 is the W-072141.**

Both part numbers listed under the JACKS/CONNECTORS/CABLES section are also incorrect. WA901 should be changed to CZDZ072141Z and WA902 to CZDZ072142Z.

WARRANT INFORMATION: No warranty procedures are necessary with this TSB.

RELM COMMUNICATIONS

7100 Technology Drive, West Melbourne, Florida 32904
800-648-0947 – Email service@RELM.com