
TECHNICAL SERVICE BULLETIN

TO: All Uniden Private Radio Communication Dealers,
Distributors and Warranty Service Stations

REFERENCE: SPH155DT, SPU454KT, SPS801TS, SPS802TS,
SPS801TSE, SPS802TSE

SUBJECT: Improved Battery Contacts

GENERAL: The original part BJKY0836002, was replaced with a new improved version. The new part number is BJKY0995002. The original part may exhibit poor conduction after a period of time due to weakened springs. One of the first signs of failure is when the battery low warning appears too soon, and the battery checks out good.

WARRANTY INFORMATION: Follow standard warranty procedures for replacement and labor reimbursement.

